

Illinois Environmental Protection Agency

Bureau of Water • 1021 N. Grand Avenue E. • P.O. Box 19276 • Springfield • Illinois • 62794-9276

Division of Water Pollution Control ANNUAL FACILITY INSPECTION REPORT

for NPDES Permit for Storm Water Discharges from Separate Storm Sewer Systems (MS4)

This fillable form may be completed online, a copy saved locally, printed and signed before it is submitted to the Compliance Assurance Section at the above address. Complete each section of this report.

Report Period: From March, 2021	To March,	2022			Permit No.	ILR40
MS4 OPERATOR INFORMATION: (As it app	ears on th	e curre	ent permit)			
Name: Rockford Township		N	lailing Addre	ss 1: 404 N. S	pringfield Av	e
Mailing Address 2:				(County: Wir	nnebago
City: Rockford	State:	IL	Zip: 6110	1	Telephone: 8	15-962-7313
Contact Person: Barry Palm (Person responsible for Annual Report)		Ema	il Address:	Barrypalm@r	ockfordtown	shipil.gov
Name(s) of governmental entity(ies) in which	MS4 is loc	ated:	(As it appe	ars on the cur	rent permit))
Rockford Township						
THE FOLLOWING ITEMS MUST BE ADDRESS	ED.					
A. Changes to best management practices (check regarding change(s) to BMP and measurable states.)		ate BN	IP change(s) and attach in	formation	
1. Public Education and Outreach	□ 4	. Con	struction Site	e Runoff Contre	ol	
2. Public Participation/Involvement	☐ 5	. Pos	-Constructio	n Runoff Cont	rol	
3. Illicit Discharge Detection & Elimination	□ 6	. Poll	ution Preven	tion/Good Hou	sekeeping	
B. Attach the status of compliance with permit commanagement practices and progress towards a MEP, and your identified measurable goals for	achieving t	he sta	tutory goal o	f reducing the		
C. Attach results of information collected and ana					ng the report	ing period.
D. Attach a summary of the storm water activities implementation schedule.)	you plan t	o und	ertake during	g the next repo	rting cycle (i	ncluding an
E. Attach notice that you are relying on another g	overnment	entity	to satisfy so	ome of your pe	rmit obligatio	ns (if applicable).
F. Attach a list of construction projects that your e	entity has p	aid fo	r during the	reporting perio	d.	
Any person who knowingly makes a false, fictitious commits a Class 4 felony. A second or subsequen						
Barry Falm Owner Signature:				6/1 Date:	12021	missioner
Barry J. Kalm Printed Name:	-		<u> Pep</u>	uty Highu Title:	vay Com	missioner

EMAIL COMPLETED FORM TO: epa.ms4annualinsp@illinois.gov

or Mail to: ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

WATER POLLUTION CONTROL

COMPLIANCE ASSURANCE SECTION #19

1021 NORTH GRAND AVENUE EAST

POST OFFICE BOX 19276

SPRINGFIELD, ILLINOIS 62794-9276

This Agency is authorized to require this information under Section 4 and Title X of the Environmental Protection Act (415 ILCS 5/4, 5/39). Failure to disclose this information may result in: a civil penalty of not to exceed \$50,000 for the violation and an additional civil penalty of not to exceed \$10,000 for each day during which the violation continues (415 ILCS 5/42) and may also prevent this form from being processed and could result in your application being denied. This form has been approved by the Forms Management Center.

Rockford Township Highway --- March 2021

Attachment to the IEPA Annual Facility Inspection Report

for the

NPDES Permit for Storm Water Discharges from MS4s Permit No. ILR40-0118

Report Period: March 2021 - March 2022

Part I

No change

Part II

A. Public Education and Outreach

- 1.) Incorporating educational articles and materials at both the office and on the website.
- 2.) Continue working with Township web site director to add annual facility inspection report to website and provide link to Winnebago County stormwater management website.
- 3.) Continue relations with Winnebago County soil and water to provide brochures and information to the public

B. Public Participation / Involvement

- 1.) Planned yearly meeting to discuss any storm water issues in the Township.
- 2.) Involved with South Fork Kent Creek committee.
- 3.) Make public the Township is available for any volunteer education or speaking.
- 4.) Meet with Winnebago County regularly on planning and implementing our storm water system, BMP plan.

C. Illicit Discharge Detection and Elimination

- 1.) Continued discussion with Winnebago County to help fund interns to update storm water maps.
- 2.) Train and implement visual dry weather screening of all out flows. Document findings.
- 3.) Actively involved in making improvements in drainage basin to increase the ability to assess impact areas.
- 4.) Address and document plan for water quality monitoring.
- 5.) Work with the City of Rockford and the County to identify areas of collaborative watersheds for quality monitoring.
- 6.) In cooperation with Winnebago County review and enforce Winnebago County's Surface Water Management Ordinance.

D. Construction Site Runoff

 Rockford Township has made an agreement with Winnebago County to review and field inspect all construction site, runoff control, and requirements in Winnebago County Surface Water Management Ordinance.

- 2.) Inspect and ensure all developments in Rockford Township follow NPDES guidelines and receive all necessary documents prior to approval.
- 3.) Enforce erosion and sediment control ordinances.

E. Post-Construction Runoff Control

1.) Rockford Township following Winnebago County's Surface Water Management Ordinance encourages developments that incorporate post construction runoff quality controls which benefit water quality and prevents creation of any surface water nuisances, hazards, or contamination of ground water.

F. Pollution Prevention / Good Housekeeping


- 1.) Continuous training in the proper technique of applying and disposing of chemical and salt alternatives for all employees
- 2.) Spring street sweeping of all streets with cub and gutter.
- 3.) Fall leaf sweeping and inlet cleaning.
- 4.) Employee training on proper road de-icing.
- 5.) Employee training on proper way to repair and seed draining areas.
- 6.) Start documenting all training.

G. Storm Water Activities Conducted March 2021 - March 2022


- 1.) Replaced culvert pipe east side of Carabaugh and cleaned draining ditch going north.
- 2.) In cooperation with Winnebago County, minor sod repaired at retention pond north of Plaza Road in Cherry North subdivision.
- 3.) Replaced cross culverts and rebuilt end walls Carlisle.
- 4.) Reshaped and seeded from detention pond to Radnor Dr. on Chesterfield.
- 5.) Planned repaired for end walls on cross culvert on Centerville Road.
- 6.) Replaced cross culverts and drainage repair on Columbine Dr.
- 7.) Replaced culvert and ditched 2661 Teton.
- 8.) Planned repaired outlet into Madigan Creek at 7395 Montmorency.
- 9.) Replaced culvert and ditched 3251 Summerwind Dr.
- 10.) Replaced cross culvert and ditched on Liberty at Carbaugh.
- 11.) Replaced culvert 1614 Charlotte.
- 12.) Replaced culvert 3022 Summerwind.
- 13.) Planned drainage repair Bond Ave...
- 14.) Repair with rip rap ditch on Fitzgerald leading into creek.
- 15.) Planned repair of separated concrete tube running under Windflower.
- 16.) Ditch work and open culvert on Carbaugh Avenue, guarter mile.
- 17.) Drainage work and monitoring of Lakeside Dr..
- 18.) Ditch and drainage repair Bond Ave..
- 19.) Prepped outlet repair into Madigan Creek off Montmorency Drive.
- 20.) Planned drainage repair 5230 Guilford Road.
- 21.) Storm drain repair Julia Lane.
- 22.) Inlet cleaning on Cerasus Dr..
- 23.) Inspect, clean ,and repair inlets Guilford Country Club Eastates.


H. Construction Projects


- 1.) Create retention basins for west side of property.
- 2.) In cooperation with Winnebago County work towards obtaining a grant to repair Madigan Creek.




ROCKFORD TOWNSHIP HIGHWAY DEPARTMENT SALT STORAGE FACILITY









42" x 29" x 40'	8/27/2020	Replace 2 cross culverts under Plaza
42" x 29" x 50'	8/27/2020	Replace cross culvert under Clockview
John Johnson 519-7821	8/7/2020	Add large stone under last section of pipe
		in back yard at creek - wait for ground to freeze
		Bottom shot Concrete
15"	7/24/2020	Replace tube 15 or 18 inch tube
		end of tube bent
2-48' 35"x 24"	5/12/2021	
38' x 15"	4/30/2021	
15" x 22'	5/18/2021	drop tube lower
48' x 15"	6/14/2020	
		Repair end section into madigan Creek
15" x 42'	7/30/2020	
15" x 24'	5/4/2021	
12" x 20'	4/29/2021	drive
15 x 36'	4/9/2021	
12 x 20'	4/8/2021	drive
12 × 20'	4/8/2021	drive
15x24	5/20/2021	Drive
jack heiman 262- 8345 15x22		drive
		42" x 29" x 40' 42" x 29" x 50' 15" 2-48' 35" x 24" 38' x 15" 15" x 22' 48' x 15" 15" x 24' 15" x 24' 15" x 20' 12 x 20' 12 x 20' 15x24 15x24

ADDRESS	RESIDENT	COMPLETED	NOTES
4418 Compton	Don Jarvis 980-4902		Ditching and birming
Halsted/Hazel			Ditch from Cross cmp on Halsted to cross cmp on Hazel
5252 Tipple	Pat Baxter 621-6340		
2908 Sierra			Ditch east of driveway to ditch going north (she will ditch on her property)
Maiposa			Ditch from Eleana to Dierks on the east side
St Malo	Kathy Bershire 975-0158		Ditch St Malo from Lemans to cross culvert on the south side
118 Garver	Steve Laube 871-2361		Minor ditch from garage south to intake
5230 Guilford	Terry Clinton 904-3300		Ditch from drive culvert to drive culvert - need backhoe
Nina Terr/Memorial			Open up ditch to expose culvert under Nina Terr
1615 Charlotte	Sandy Piper 397-8103		Remove hump in ditch to drain
5606 Grover	Mike Renton 962-4067		add stone to east side drive and cut down west Ditch Grover/Orchard curve
1820 Hawthorne Dr	Jay Johnson		Clean ditch and tube Skid loader
1941 Hawthorne Dr			Clean tube that crosses under Hawthorne Skid loadershovels
Vinton/Penn	Tom 608-576-1929	12/4/2020 check ir	12/4/2020 check ir water on road, low spot causing problem with 2915 Vinton
773 White Swan Ln	Vintent 668-2011		minor ditch work and wash rock
Rote Road	Fred 494-5907		North side(City) South side from Township/City line to first house
Ketchum	Mike Burkard 601-3335		ditch along north side ????????
3938 St Malo	Laurie 980-5009		Clean ditch south of drive Water should flow between houses
5890 Porter	Rita 968-7795		Clean out on south side of tube we replaced to get water to flow straighter down yard
8638 Rote			
6909 Canter Ct	Jack Heiman		Small amount of ditching
2088 Havaview	jerry Kudzma 962-4640		removed bricks and ties 12/9/2020 Check ditch in spring
8638 Rote Rd	Melissa Hughes		survey to see if a tube can be put in drivenot ergenttold her not this yr
6150 Iorilynn Ln			slight ditching
6950 Farbwood	Cecil 262-2647 Susan 262-6900		Slight ditching ??
695 Homestead	James Reynolds 968-9498		slight ditching
3956 Lakeside			Slight ditchin might have to lower tube